

## 第7讲 空间物体成像的清晰程度 ——景深

















### 一、景深的定义



能够在像面上获得清晰像的物空间深度,就是系统的景深。



### 二、公式推导



$$\frac{Z'}{D} = \frac{l' - l_1'}{l_1'}$$

$$\frac{Z'}{D} = \frac{l_2' - l'}{l_2'}$$



$$\frac{Z'}{D} = \frac{l' - l_1'}{l_1'} \qquad \longrightarrow \qquad l_1$$

$$\frac{1}{l_1'} - \frac{1}{l_1} = \frac{1}{f'}$$

$$\frac{l_1'-l'}{l_1'l'} = (\frac{1}{l} - \frac{1}{l_1})$$

两式相减并通分,得 
$$\frac{l_1'-l'}{l_1'l'} = (\frac{1}{l} - \frac{1}{l_1})$$
 或者  $l'-l_1' = (\frac{1}{l} - \frac{1}{l_1})l_1'l'$ 

代入 
$$\frac{Z'}{D}$$
 的表达式,得

$$\frac{Z'}{D} = \left(\frac{1}{l_1} - \frac{1}{l}\right)l'$$



$$\frac{Z'}{D} = (\frac{1}{l_1} - \frac{1}{l})l'$$

由上式求解 
$$\frac{1}{l_1}$$
, 并将  $\frac{1}{l'}$ 用  $\frac{1}{l} + \frac{1}{f'}$ 代替得  $\frac{1}{l_1} = \frac{1}{l} + \frac{Z'}{D}(\frac{1}{l} + \frac{1}{f'})$ ——远景平面

同理, 
$$\frac{1}{l_2} = \frac{1}{l} - \frac{Z'}{D} (\frac{1}{l} + \frac{1}{f'}) \quad ---近景平面$$

两式相减,



#### 三、性质

$$\frac{1}{l_1} - \frac{1}{l_2} = \frac{2Z'}{D} \left( \frac{1}{l} + \frac{1}{f'} \right)$$

- 1、容许的光斑直径越大,景深越大;
- 2、照相物镜的相对孔径与焦距和景深的关系:

$$\frac{1}{l_1} - \frac{1}{l_2} \approx \frac{2Z'}{D} \frac{1}{f'} = \frac{2Z'}{\left(\frac{D}{f'}\right) f'^2}$$

景深与相对孔径成反比。





1:2.8



1:8



1:16

不同相对孔径的效果

大景深: 如需要拍远景,应选择:

短焦距 小相对孔径 对准距离远

小景深: 如需要拍特写, 应选择:

长焦距 大相对孔径 对准距离近





# <u>应用</u>:若要求最远的清晰范围直到无限远,确定基准物平面、近景平面位置和总成像深度

将
$$l_1 = -\infty$$
代入 $\frac{1}{l_1} = \frac{1}{l} + \frac{Z'}{D}(\frac{1}{l} + \frac{1}{f'})$ ,用 $l_\infty$ 表示 $l$ ,得
$$\frac{1}{l_\infty} = -\frac{Z'}{Df'} \frac{1}{1 + \frac{Z'}{D}}$$

#### 最近的清晰物平面位置用 $l_{2\infty}$ 表示,即 $l_2 = l_{2\infty}$

代入 
$$\frac{1}{l_2} = \frac{1}{l} - \frac{Z'}{D} (\frac{1}{l} + \frac{1}{f'})$$
, 得 
$$\frac{1}{l_{2\infty}} = -\frac{2Z'}{Df'} \frac{1}{1 + \frac{Z'}{D}} = \frac{2}{l_{\infty}} \qquad \text{由无限远到} \ l_{2\infty}$$
 即为总的成像深度。