



TO-92 PACKAGE OUTLINE DIMENSIONS






Symbol	Dimensions	In Millimeters	Dimensions In Inches		
Symbol	Min	Max	Min	Max	
Α	3.300	3.700	0.130	0.146	
A1	1.100	1.400	0.043	0.055	
b	0.380	0.550	0.015	0.022	
С	0.360	0.510	0.014	0.020	
D	4.300	4.700	0.169	0.185	
D1	3.430		0.135		
E	4.300	4.700	0.169	0.185	
е	1.270	TYP.	0.050	TYP.	
e1	2.440	2.640	0.096	0.104	
L	14.100	14.500	0.555	0.571	
Ф		1.600		0.063	
h	0.000	0.380	0.000	0.015	







TO-92 PACKAGE TAPEING DIMENSION







Dimiensions are in millimeter								
A1	Α	Т	Р	P0	P2	F1	F2	W
4.5±0.2	4.5±0.2	3.5±0.2	12.7±0.3	12.7±0.2	6.35±0.3	2.5±0.3	2.5±0.3	18.0+1.0/-0.5
W0	W1	W2	Н	H0	D0	t1	t2	ΔΡ
6.0±0.5	9.0±0.5	1.0 MAX.	19.0+2.0/-1.0	16.0±0.5	4.0±0.2	0.4±0.05	0.2±0.05	0 ± 1.0



Package	Вох	Box Size(mm)	Carton	Carton Size(mm)
TO-92	2000 pcs	333×162×43	20,000 pcs	350×340×250

TO-92 PACKAGE TAPING DIMENSION

Item	Symbol	Value & Tolerance
Body width	A1	4.5 ± 0.2
Body height	А	4.5 ± 0.2
Body thickness	Т	3.5 ± 0.2
Lead wire diameter	d	0.46 +0.09,-0.08
Pitch of component	Р	12.7 ± 0.3
Feed hole pitch	P0	12.7 ± 0.2
Hole center to component center	P2	6.35 ± 0.3
Lead to lead distance	F1,F2	2.5 ± 0.3
Component alignment, F-R	$\triangle h$	0 ± 1.0
Type width	W	18.0 + 1.0, - 0.5
Hole down tape width	W0	6.0 ± 0.5
Hole position	W1	9.0 ± 0.5
Hole down tape position	W2	1.0 MAX.
Height of component from tape center	Н	19.0+2.0,-1.0
Lead wire clinch height	H0	16.0 ± 0.5
Lead wire(tape portion)	L1	2.5 MIN.
Feed hole diameter	D0	4.0 ± 0.2
Taped Lead Thickness	t1	0.4 ± 0.05
Carrier Tape Thickness	t2	0.2 ± 0.05
Position of hole	P1	3.85 ± 0.3
Component alignment	△P	0 ± 1.0
		Unit : mm



