
Energy accounting includes external torque work
Energy / work (J)
0.0
0.1
0.2
0.3
0.4
0.5
0.6
Electrical input
Copper loss
Bearing loss
External body work
Stored energy change
1e−8
Work-balance defect (J)
0.0
0.5
1.0
1.5
2.0
2.5
0.0
2.5
5.0
7.5
10.0
12.5
15.0
17.5
20.0
Time (s)