
A recoverable pulse and an uncommandable stuck driver
pulse
stuck positive
Body angle (rad)
direct
cascaded
feedforward
target
Motor current (A)
hard current limit
Relative wheel speed (rad/s)
hard speed limit
soft speed gate
Time (s)
Time (s)