

Outlet temperature 3000 4000 5000 Bearing temperature 43.2 43 42.8 42.6 42.4 3000 4000 5000 Temperature of hot primary air 3000 4000 5000 Temperature of cold air Samples (b) Other variables

Fig. S5. Practical data from coal pulverizing system