

Problem Description

Controller restarts when CAN message volume increases.

TRC Occurrence

The receive queue has no bounded filtering and protection bit handling is incorrect.

Root Cause

All bus IDs are processed, causing congestion and self-protection restart.

Preventive Actions

Add ID whitelist, queue limit, overload monitoring and stress tests.