"In order to be compatible with this specification an implementation must:

   …

   2. Implement at least one of Program Buffer, System Bus Access, or Abstract Access Memory

   …
"

The RISC-V Debug Specification, Version 1.0.0-rc3

Program Buffer