Minimum Viable Debugger Hardware

What Do We Need for a Debugger?

Bare Minimum Hardware Requirements

Memory

- Peek
- Poke

Registers

- Read
- Write

Control

- Halt
- Step
- Reset
- Break