

5V
GROUMY
CLOCK
SOO
SOT
CS
SOJ

F

A-5V A-GND A-13 A-12 H-11 A-10

19-4 B-4 B-50 B-12 B-23 B-34 B-44 8-19 6-26 B-37

SV supply
Ground supply
Clock supply
SNO supply
SNT supply
CS of
CS of
CS &
SOA barometar

SCL baremeter

SV to B

SV to

E

Key

A-10 = Aduino pin 10

13-25= Breadbard 10W 29