

Supplier Technical Bulletins (Archive)

Bulletins issued by our fittings supplier over time. Kept for reference — note that specifications can change between bulletins as the manufacturer updates products, and the most recent bulletin does not automatically override what is in our current product catalog (the catalog is updated separately when we confirm changes with the supplier, sometimes with a delay).

Bulletin #14 — March 2024

Subject: Pressure-Limiting Valve (PLV) product line update

The PLV accessory (our code PC-111) has an adjustable output range of 200–450 kPa. Recommended for installations where incoming mains pressure exceeds 900 kPa. Warranty remains 5 years, unchanged from prior stock.

Bulletin #19 — November 2024

Subject: Wall-Faced Toilet Suite minimum inlet pressure correction

Manufacturer testing has revised the minimum inlet pressure for the in-wall cistern mechanism (our code TL-302) down to 35 kPa, from the previously listed 50 kPa. This makes the unit compatible with a wider range of gravity-fed installations than earlier documentation suggested. No change to maximum inlet pressure or warranty terms.

Bulletin #23 — June 2025

Subject: PLV output range revision

Following a manufacturing tolerance adjustment, the PLV (PC-111) adjustable output range is now specified as 250–500 kPa, replacing the range given in Bulletin #14. Installers should treat this as the current figure. Existing stock manufactured before this bulletin may still carry old-range documentation in the box — the printed range on paperwork inside older stock does not reflect this update.

Staff Note (added by store management, not part of the original bulletins)

Our current product catalog lists the TL-302 minimum inlet pressure as 50 kPa — this has not yet been updated to match Bulletin #19's revised figure of 35 kPa, pending confirmation from the supplier that the correction applies to the exact model variant we stock (there are two very similar TL-302 variants and we want to confirm before changing customer-facing documentation). Until that confirmation comes through, staff should continue quoting 50 kPa as the safe minimum when advising customers, even though a more permissive figure exists in the bulletin archive.

For the PLV, the catalog's 250–500 kPa range does match the latest bulletin (#23) — no discrepancy there.