

Report no.: 25-006692-KL	Job No.: -	Project no.: P000161	Date: 24 Nov. 2025	Office: Kuala Lumpur
------------------------------------	---------------	--------------------------------	------------------------------	--------------------------------

CERTIFICATE OF INSPECTING AUTHORITY

I **RIZAL BIN MOHAMED UDRUS** BEING AN INSPECTOR OF **APAVE TIV MALAYSIA SDN. BHD.** AN INSPECTING AUTHORITY NAMED IN THE FIRST SCHEDULE OF **OCCUPATIONAL SAFETY AND HEALTH ACT 1994, (PLANT REQUIRING CERTIFICATE OF FITNESS, REGULATIONS 2024), P.U. (A) 99**, HEREBY CERTIFY THAT THE STEAM BOILER/PRESSURE VESSEL WAS CONSTRUCTED AND WAS SURVEYED DURING CONSTRUCTION BY ME AND SCANTLINGS ARE IN ACCORDANCE WITH **ASME SECTION I 2023 EDITION** (BEING A STD NAMED IN THE FOURTH SCHEDULE TO THE AFOREMENTIONED REGULATIONS),

MANUFACTURER	:	SHANGHAI BOILER WORKS CO., LTD.
MANUFACTURER ADDRESS	:	250 HUANING ROAD, MINHANG DISTRICT, SHANGHAI, P.R. OF CHINA. 200245 MINHANG SHANGHAI CHINA.
TYPE OF PLANT/ NAME OF PLANT	:	WASTE HEAT BOILER
PLANT ADDRESS	:	JERAM WTE 2 PROJECT LOT 2956, BATU 3 1/2, JALAN BUKIT KERAYONG, MUKIM JERAM, 45800 DAERAH KUALA SELANGOR, SELANGOR, MALAYSIA.
OWNER NAME	:	WORLDWIDE ENVIROGREEN SDN. BHD.
OWNER ADDRESS	:	JERAM WTE 2 PROJECT LOT 2956, BATU 3 1/2, JALAN BUKIT KERAYONG, MUKIM JERAM, 45800 DAERAH KUALA SELANGOR, SELANGOR, MALAYSIA.
NAME OF OCCUPIER	:	WORLDWIDE ENVIROGREEN SDN. BHD.
ADDRESS OF OCCUPIER	:	JERAM WTE 2 PROJECT LOT 2956, BATU 3 1/2, JALAN BUKIT KERAYONG, MUKIM JERAM, 45800 DAERAH KUALA SELANGOR, SELANGOR, MALAYSIA.
YEAR OF MANUFACTURE	:	2025
DESIGN VERIFICATION NUMBER	:	JKKP/2024/02/T-01/00038
DESIGN VERIFICATION DATE	:	24/09/2024
TYPE OF PRESSURE TEST	:	HYDROSTATIC TEST
DATE OF PRESSURE TEST	:	20/11/2025
LOCATION OF PRESSURE TEST	:	JERAM WTE 2 PROJECT LOT 2956, BATU 3 1/2, JALAN BUKIT KERAYONG, MUKIM JERAM, 45800 DAERAH KUALA SELANGOR, SELANGOR, MALAYSIA.
APPLIED PRESSURE TEST	:	7245.00 kPa / 1050.76 psi

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and the liability of Apave TIV Malaysia or Apave SA shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall Apave TIV Malaysia or Apave SA be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment, or other items other than such defects ascertainable by normally accepted testing standards and only upon those items inspected by Apave TIV Malaysia or Apave SA and which are covered by this Report.

Report no.: 25-006692-KL	Job No.: -	Project no.: P000161	Date: 24 Nov. 2025	Office: Kuala Lumpur
------------------------------------	---------------	--------------------------------	------------------------------	--------------------------------

HOLDING TIME	:	20 MINUTES
DESIGN PRESSURE (kPa)	:	STEAM DRUM : 4830.00 kPa / 700.51 psi EVAPORATOR I & II: 5130.00 kPa / 744.02 psi SUPERHEATER I, II, III : 4830.00 kPa / 700.51 psi ECONOMIZER I, II, III, IV & V : 5130.00 kPa / 744.02 psi DESUPERHEATER I & II : 4830.00 kPa / 700.51 psi
SAFE WORKING PRESSURE (kPa)	:	STEAM DRUM : 4830.00 kPa / 700.51 psi EVAPORATOR I & II: 5130.00 kPa / 744.02 psi SUPERHEATER I, II, III : 4830.00 kPa / 700.51 psi ECONOMIZER I, II, III, IV & V : 5130.00 kPa / 744.02 psi DESUPERHEATER I & II : 4830 kPa / 700.51 psi
CAPACITY (M3) (pressure vessel)	:	N/A
HEATING SURFACE (M2) (boiler)	:	3, 404.000 Meter Persegi
TYPE OF PRESSURE VESSEL/STEAM BOILER (fire tube/water tube/electric steam boiler/autoclave)	:	WASTE HEAT BOILER (2x750t/d MEDIUM PRESSURE WASTE HEAT BOILER)
SERIAL NO.	:	SH23-005 MODEL: SG-SLC750-81.6/4.12/400-8928
ACCORDANCE TO DRAWING NOS.	:	1. 5108928-E1-01 Rev. 0 2. 5108928-C1-01 Rev. 0 3. 5108928-B1-01001 Rev. 0 4. 5108928-B1-01003 Rev. 0 5. 5108928-C1-01002 Rev. 0 6. 5208928-E1-01 Rev. 0 7. 5208928-E1-02 Rev. 0 8. 5208928-E1-03 Rev. 0 9. 5208928-E1-04 Rev. 0 10. 5208928-E1-05 Rev. 0 11. 5208928-E1-06 Rev. 0 12. 5208928-E1-07 Rev. 0 13. 5208928-D1-08 Rev. 0 14. 5208928-D1-09 Rev. 0 15. 5228928-D1-01 Rev. 0 16. 5228928-D1-02 Rev. 0 17. 5228928-D1-03 Rev. 0 18. 5228928-D1-04 Rev. 0 19. 5228928-D1-05 Rev. 0 20. 5228928-D1-06 Rev. 0 21. 5228928-D1-07 Rev. 0 22. 5228928-C1-08 Rev. 0 23. 5228928-C1-09 Rev. 0

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and the liability of Apave TIV Malaysia or Apave SA shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall Apave TIV Malaysia or Apave SA be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment, or other items other than such defects ascertainable by normally accepted testing standards and only upon those items inspected by Apave TIV Malaysia or Apave SA and which are covered by this Report.

Report no.:
25-006692-KLJob No.:
-Project no.:
P000161Date:
24 Nov. 2025Office:
Kuala Lumpur

24. 5228928-C1-10 Rev. 0
25. 5228928-D1-11 Rev. 0
26. 5228928-D1-12 Rev. 0
27. 5228928-D1-13 Rev. 0
28. 5228928-D1-14 Rev. 0
29. 5228928-D1-15 Rev. 0
30. 5228928-D1-16 Rev. 0
31. 5228928-D1-17 Rev. 0
32. 5228928-D1-18 Rev. 0
33. 5228928-D1-19 Rev. 0
34. 5228928-D1-20 Rev. 0
35. 5228928-D1-21 Rev. 0
36. 5228928-D1-22 Rev. 0
37. 5268928-E1-01 Rev. 0
38. 5268928-E1-02 Rev. 0
39. 5268928-D1-01001 Rev. 0
40. 5268928-D1-01006 Rev. 0
41. 5268927-D1-02001 Rev. 0
42. 5268928-D1-02005 Rev. 0
43. 5268928-C1-01002 Rev. 0
44. 5268928-C1-01003 Rev. 0
45. 5268928-C1-01004 Rev. 0
46. 5268928-C1-01007 Rev. 0
47. 5268928-C1-01008 Rev. 0
48. 5268928-C1-01009 Rev. 0
49. 5268928-C1-02002 Rev. 0
50. 5268928-C1-02003 Rev. 0
51. 5268928-C1-02004 Rev. 0
52. 5268928-C1-02006 Rev. 0
53. 5268928-C1-02007 Rev. 0
54. 5268928-C1-02008 Rev. 0
55. 5268928-E1-03 Rev. 0
56. 5268928-D1-03001 Rev. 0
57. 5268928-D1-03002 Rev. 0
58. 5268928-D1-03003 Rev. 0
59. 5268928-D1-03004 Rev. 0
60. 5268928-D1-03005 Rev. 0
61. 5268928-D1-03006 Rev. 0
62. 5268928-D1-03007 Rev. 0
63. 5268928-D1-03008 Rev. 0
64. 5268928-D1-03009 Rev. 0
65. 5268928-D1-030010 Rev. 0

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and the liability of Apave TIV Malaysia or Apave SA shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall Apave TIV Malaysia or Apave SA be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment, or other items other than such defects ascertainable by normally accepted testing standards and only upon those items inspected by Apave TIV Malaysia or Apave SA and which are covered by this Report.

Report no.: 25-006692-KL	Job No.: -	Project no.: P000161	Date: 24 Nov. 2025	Office: Kuala Lumpur
------------------------------------	----------------------	--------------------------------	------------------------------	--------------------------------

66. 5408928-D1-030011 Rev. 0
67. 5408928-D1-03011 Rev. 0
68. 5408928-D1-01 Rev. 0
69. 5408927-D1-01001 Rev. A
70. 5408928-D1-02 Rev. 0
71. 5408927-D1-02001 Rev. 0
72. 5428928-D1-03 Rev. 0
73. 5428927-D1-03001 Rev. 0
74. 5428928-D1-01 Rev. 0
75. 5428928-D1-02 Rev. 0
76. 5428927-A1-06002 Rev. 0
77. 5428928-D1-03 Rev. 0
78. 5428928-D1-04 Rev. 0
79. 5428928-D1-05 Rev. 0
80. 5428928-D1-06 Rev. 0
81. 5428928-D1-07 Rev. 0
82. 5608928-E1-01 Rev. 0
83. 5608927-D1-01001 Rev. 0
84. 5608927-D1-01014 Rev. 0
85. 5628927-D1-01022 Rev. 0
86. 5628928-D1-01 Rev. 0
87. 5628928-D1-02 Rev. 0
88. 5628928-D1-03 Rev. 0
89. 5628928-D1-04 Rev. 0
90. 5628928-D1-05 Rev. 0
91. 5808928-D1-01 Rev. 0
92. 5808928-D1-02 Rev. 0
93. 5008928-E1 Rev. 0
94. 5018928-E1-10 Rev. 0
95. 5128928-D1-01 Rev. 0
96. 5128928-C1-02 Rev. 0
97. 5128928-B1-01001 Rev. 0
98. 5128928-B1-01003 Rev. 0
99. 5128927-B1-02001 Rev. 0
100. 5128927-B1-02004 Rev. 0
101. 5128928-C1-01004 Rev. 0
102. 5128928-C1-01011 Rev. 0
103. 7808928-D1-01 Rev. 0
104. 7808928-D1-02 Rev. 0
105. 7808928-D1-03 Rev. 0
106. 7808928-D1-04 Rev. 0
107. 7808928-D1-05 Rev. 0

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and the liability of Apave TIV Malaysia or Apave SA shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall Apave TIV Malaysia or Apave SA be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment, or other items other than such defects ascertainable by normally accepted testing standards and only upon those items inspected by Apave TIV Malaysia or Apave SA and which are covered by this Report.

Report no.:
25-006692-KLJob No.:
-Project no.:
P000161Date:
24 Nov. 2025Office:
Kuala Lumpur

- 108. 7808928-D1-06 Rev. 0
- 109. 7808928-B1-02020 Rev. 0
- 110. 7808928-B1-02021 Rev. 0
- 111. 7808928-B1-03001 Rev. 0
- 112. 7808928-B1-03002 Rev. 0
- 113. 7808928-B1-03003 Rev. 0
- 114. 7808928-B1-04001 Rev. 0
- 115. 7808928-B1-05001 Rev. 0
- 116. 7808928-B1-06002 Rev. 0
- 117. 7808928-C1-01003 Rev. 0
- 118. 7808928-C1-02001 Rev. 0
- 119. 7808928-C1-02008 Rev. 0
- 120. 7808928-C1-02015 Rev. 0
- 121. 7808928-C1-02019 Rev. 0
- 122. 7818928-D1-01 Rev. 0
- 123. 7818928-D1-02 Rev. 0
- 124. 7818928-D1-03 Rev. 0
- 125. 7818928-B1-01013 Rev. 0
- 126. 7818928-B1-01018 Rev. 0
- 127. 7818928-B1-02005 Rev. 0
- 128. 7818928-B1-02006 Rev. 0
- 129. 7818928-B1-02007 Rev. 0
- 130. 7818928-B1-02008 Rev. 0
- 131. 7818928-C1-01004 Rev. 0
- 132. 7818928-C1-01010 Rev. 0
- 133. 7818928-C1-01012 Rev. 0
- 134. 7818928-C1-01014 Rev. 0
- 135. 7818928-D1-01001 Rev. 0
- 136. 7818928-D1-01007 Rev. 0
- 137. 7818928-D1-01016 Rev. 0
- 138. 7908928-C1-01 Rev. 0
- 139. 7908928-D1-02 Rev. 0
- 140. 7908928-B1-03 Rev. 0
- 141. 7908927-B1-01009 Rev. 0
- 142. 7908927-B1-02001 Rev. 0
- 143. 7908927-B1-02004 Rev. 0
- 144. 7908927-B1-02005 Rev. 0
- 145. 7908927-B1-02008 Rev. 0
- 146. 7908928-B1-02001 Rev. 0
- 147. 7908928-C1-01001 Rev. 0
- 148. 8208928-E1-01 Rev. 0
- 149. 8208928-E1-02 Rev. 0

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and the liability of Apave TIV Malaysia or Apave SA shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall Apave TIV Malaysia or Apave SA be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment, or other items other than such defects ascertainable by normally accepted testing standards and only upon those items inspected by Apave TIV Malaysia or Apave SA and which are covered by this Report.

Report no.: 25-006692-KL	Job No.: -	Project no.: P000161	Date: 24 Nov. 2025	Office: Kuala Lumpur
------------------------------------	----------------------	--------------------------------	------------------------------	--------------------------------

150. 8208928-D1-03 Rev. 0
151. 8208928-C1-04 Rev. 0
152. 8208928-D1-05 Rev. 0
153. 8208928-D1-06 Rev. 0
154. 8508928-C1-01 Rev. 0

IT SHOWED NO SIGNS OF WEAKNESS AND FOUND TIGHT AND SOUND IN EVERY RESPECT AT THAT PRESSURE. IT WAS STAMPED BY ME AS FOLLOWS:

NIL

.....
DATED THIS **20 DAY OF NOVEMBER 2025**

RIZAL BIN MOHAMED UDRUS

.....
INSPECTOR NAME



.....
INSPECTOR SIGNATURE

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and the liability of Apave TIV Malaysia or Apave SA shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall Apave TIV Malaysia or Apave SA be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment, or other items other than such defects ascertainable by normally accepted testing standards and only upon those items inspected by Apave TIV Malaysia or Apave SA and which are covered by this Report.