

Product: RTL88x2C USB Wi-Fi Software Package - Linux Driver v5.12.1-14-ge3f808d.20201214_COEX20200922-1e1e

Release History:

| Version | Summary |
|-------------------------|---|
| v5.7.3_33533.20190527_ | 1. First formal release driver and software package |
| COEX20190403-0c0c | |
| v5.7.3.3_35623.20191031 | 1. Fix PLL is too fast by updating power sequence. |
| _COEX20190531-0e0e | 2. Fix compile error for kernel 5.3. |
| | 3. Update coex. version to v0e |
| | 4. Sync correct crystal_cap value into the corresponding hw |
| | efuse fields |
| v5.9.0_36035.20191217_ | 1. Update coex. version to v15 |
| COEX20191120-1515 | 2. Update PHY parameter |
| | 3. Update FW to v9.4 |
| | 4. Support 8822CU-VN |
| | 5. Support Android 10 |
| v5.9.0.1_36324.20200224 | 1. Update FW to v9.7 |
| _COEX20200103-1717 | 2. Fix LPS power saving issue |
| | 3. Update coex. Version to v17 |
| | 4. Support WPA3-SAE (Personal) |
| v5.9.0.4_36631.20200423 | 1. Update FW to v9.9 for new FW dbg function |
| _COEX20200103-1717 | 2. Support dynamic tx power(DTP) |
| | 3. Fix Kr00k issue |
| v5.12.1-14- | 1. Support Android 11 |
| ge3f808d.20201214_COE | 2. Support 8822CU-VB and 8822CU-VBN |
| X20200922-1e1e | 3. Support Agile Multiband |
| | 4. Support Manual TPC |
| | 5. Update FW to v9.12 |
| | 6. Update coex. version to v1e |



Description:

■ Realtek provides the solution for WLAN in hardware and software. The software package could be adopted for Realtek RTL88x2C USB WLAN series hardware on Linux based platforms.

Software Version:

RTL88x2C USB Linux Driver Version: v5.12.1-14-ge3f808d.20201214 COEX20200922-1e1e

Software Package Feature:

- IEEE 802.11 a/b/g/n/ac Wi-Fi compliant
- 802.1x, WEP, WPA TKIP and WPA2 AES/Mixed mode for PSK and TLS (Radius)
- WPS PIN and PBC Methods
- IEEE 802.11 a/b/g/n/ac Client mode
 - Support wireless security for WEP, WPA TKIP and WPA2 AES PSK, and WPA3-SAE (Personal)
 - Support site survey scan and manual connect
 - Support WPA/WPA2 TLS client
 - Support power saving mode
- Soft AP mode
- WiFi-Direct and Miracast
- TDLS function
- Support CE-RED v2.1.1 (2G) / v2.1.0 (5G)

Hardware Supported:

■ RTL8822CU / RTL8812CU

Platform Supported:

- Linux (kernel $2.6.24 \sim 5.8$)
- Android 4.4, 6.x, 7.0, 8.0, 9.x, 10, 11

CPU supported:

- x86
- ARM
- MIPS