







before handover: leg j loaded



after: $f_j = 0$, body unchanged



○ commanded foot position

$\sum_i w_i = 1$: six-command mean unchanged

(c) zero-force handover (side view; vent follows)