Coman Board Numbers

1-3	Waist
4-5	Hips
6-10	Right Leg
11-15	Left Leg
16-19	Right Arm
20-23	Left Arm
24-25	Neck (not used)
26-28	Right Forearm
29-31	Left Forearm
32	Right Hand
33	Left Hand
34	Right foot FT6 sensor (was 26)
35	Left foot FT6 sensor (was 27)
36	Right forearm FT6 sensor
37	Left forearm FT6 sensor