

1.6





TECHNICAL REQUIREMENTS
1. Mark the drawing number on the workpiece. All dimensions are final dimensions.
2. Surfaces shall be smooth and free of scratches, dents, burrs and other visible defects.
3. Use 100-mesh fine abrasive for sandblasting.
4. All dimensions are in mm.

GENERAL TOLERANCES (UNLESS OTHERWISE SPECIFIED)

X.	± 0.2	X.°	± 1°
.X	± 0.10	.X°	± 0.5°
.XX	± 0.05	.XX°	± 0.1°
.XXX	± 0.02	.XXX°	± 0.01°

For sheet metal, welding, casting, stamping and similar processes, unspecified linear and geometric tolerances shall conform to in-house standards.

MATERIAL: WHITE POM
FINISH
QTY

EQUIPMENT NAME: Crown to HSG
EQUIPMENT NO.
APPROVED
CHECKED
DESIGNED
DRAWN
DATE

BARCODE
DRAWING NO.

SCALE	SHEET	REV.
2:1	1/1	X01