OTHER SURFACES 6.3





TECHNICAL REQUIREMENTS
1. Break sharp edges and remove burrs.
2. Unspecified chamfers: C0.5.

					PART NAME	DRAWING NO.
						BARCODE
MARK	QTY	CHANGE DOC. NO.	SIGNATURE	DATE	MATERIAL	
DESIGNED			DATE		Q235	DRAWING STATUS / WEIGHT / SCALE
CHECKED			DATE			A / 1:1
PROCESS			DATE		FINISH	1 SHEETS TOTAL / SHEET 1
STANDARDIZED			DATE		RAL7035 (FLAT FINISH)	DOCUMENT CLASSIFICATION
APPROVED			DATE			