




OTHER SURFACES 6.3











TECHNICAL REQUIREMENTS
1. FIRST-ANGLE PROJECTION
2. Break sharp edges and remove burrs.
3. WELD SECURELY AND FINISH WELDS SMOOTH; PLAN THE WELDING PROCESS TO PREVENT DISTORTION DIMENSIONS SHOWN ARE FINAL DIMENSIONS
4. All holes without a specified depth are through holes.
5. Unspecified dimensional tolerances for holes, slots and similar features: H11.
6. Unspecified dimensional tolerances for shafts, external profiles and similar features: h11.
7. Unspecified geometric tolerances: refer to GB/T1184-K.
8. Refer to the digital model for unspecified chamfers and fillets.

					PART NAME	DRAWING NO.
						BARCODE
MARK	QTY	CHANGE DOC. NO.	SIGNATURE	DATE	MATERIAL	
DESIGNED			DATE		SUS304	DRAWING STATUS: A; WEIGHT: ; SCALE: 1:1
CHECKED			DATE			1 SHEETS TOTAL; SHEET 1
PROCESS			DATE		FINISH	
STANDARDIZED			DATE			DOCUMENT CLASSIFICATION
APPROVED			DATE			