

www.ExtraEFI.co.uk



36-1 wheel (silver disc) in place on a RV8 flywheel between rear of damper and rear pulley.

Note: Mark all parts before splitting pulley (white marks), then realign marks on re-assembling to ensure everything goes back the same as it was.

www.ExtraEFI.co.uk