

PS-532 Pocket scale

Features:

Automatically turning off: 1 minute

Operation temperature: 10°C ~ 30°C

LCD display: 5 digit display

Back light: blue (other options)

• Dimensions: 128x78x19mm

Power: 2x "AAA" batteries

· Weight: 128g

Super stainless tray: 69x64mm

Tare function

 Automatically & low-energy-consuming alarming system

Options units: g/oz/ozt/dwt/ct/gn



G	Oz	Ct	Ozt	dwt	gn
300/0.01g	7.040oz/ 0.001oz	1000.00ct/ 0.05ct	6.440ozt/ 0.001ozt	128.80dwt/ 0.01dwt	3086.4/0.1gn