## Cosmetic requirements for surfaces indicated in BLUE


- No scratches, dents, marks
- Consistent anodization finish: no discoloration, no blemishes
- No hanging/hook marks


See included QC.PDF for more detail

## Part list:

- bottom.step
- top.step
- (2x) weight-inside.step
- weight-outside.step
- cf-accent.step


Scale Sheet 1:1 1 OF 13






Scale overall assembly


Sheet 2 OF 13








total 16 taps on this side


5	Scale	top stop book
	1:2	top.step - back














cosmetic requirements for surfaces indicated in BLUE see first page and QC.PDF for details





bottom.step - cosmetic surf.


Sheet 8 OF 13














note: side with countersunk is the cosmetic surface

cosmetic requirements for surfaces indicated in BLUE see first page and QC.PDF for details

Scale	cf-accent.step - cosmetic surfaces	Sheet
1:2		13 OF 13