```
.INCLUDE "M32DEF.INC"
  .ORG 0
  RJMP main
  .ORG $004
  RJMP rout_0
  .ORG $100
main: SBI DDRA,1
  CBI DDRD,3
  CLR R16
  SER R17
  OUT SFIOR, R16
  OUT PORTD, R17
  LDI R16,$80
  LDI R17,$00
  LDI R18,246
  LDI R19,$01
  OUT TCNT0,R18
  OUT GICR, R16
  OUT MCUCR,R17
  LDI R21,0
  LDI R22,$05
  OUT SPH, R22
  OUT SPL, R21; SP= 0500 h
  SEI
wait: RJMP wait
rout_0: OUT TCCR0, R19
  SBI PORTA, 1
wait2: IN R16, TIFR
  SBRS R16,0
  RJMP wait2
```

CBI PORTA,1

CLR R17

OUT TIFR, R19

OUT TCCR0, R17

OUT TCNT0,R18

RETI

RJMP wait2