



Dyson Service Center Repair Invoice

Official Dyson Authorized Service Center

SERVICE CENTER INFO

Dyson Service Center
Authorized Repair Station
Contact: support@dyson.com

REPAIR DETAILS

Repair Invoice: DYS-44021
Service Date: 2026-08-30
Customer Name: Manan Yadav

Product: Dyson V15 Detect Cordless Vacuum

Model: SV22

Diagnosis / Issue: Battery fault; unit powers down under load.
Service Action: Replaced defective click-in battery pack assembly.

Line Item	Cost (USD)
Dyson SV22 Replacement Battery Pack Assembly	\$ 180.00
TOTAL PAID	USD \$ 180.00

Note: Serial number label photo not provided at time of service.