

Trimmed CAD
NURBS/B-rep
trim curves
operator curves
Registered retained domain
retained parametric regions
outer and hole loops
shared operator queries
Geometry based starting settings
feature informed control grid
holes, slivers and bridges
Quadrature routing
Gaussian rules or triangulation
safeguarded subcell masking
Physical interface admission
CAD kernel candidates
retained side and coverage checks
Work consistent assembly
shell stiffness
fiber stress recovery
loads and weak boundaries
nonmatching interfaces
Nitsche coupling
Independent geometry / work / refinement checks