
Cisco WLC 9800 on Windows 11

Topology



Vmware connection: connection from windows 10 PC for config and troubleshooting. Optional.

Catalyst Switch Config

```
interface GigabitEthernet1/0/3
  no switchport
  ip address 192.168.0.199 255.255.255.0

interface GigabitEthernet 1/0/3 ~ 4
  switchport mode access
  spanning-tree portfast edge

interface Vlan1
  ip address 192.168.1.1 255.255.255.0

ip route 0.0.0.0 0.0.0.0 192.168.0.1
```


WLC Install



Install on Windows 10

- Windows 10
 - On Virtual BOX → failed
 - On Vmware Workstation → Okay
 - Trunk 802.1Q didn't work → Use VLAN 1 only → maybe realtek NIC issue, I guess.
- Download iso from cisco.com
- Vmware workstation config
 - 2.x linux 64 bit, 8Mbps mem, 40G storage, 4 vCPU
 - Add one more nic : one for wired and one for vmware host (optional)

virtual NIC type change




- Do not use notepad.
- Use notepad++!


Initial WLC CLI config (for web connetion and telnet)

```
hostname vWLC_17.9.4a
no ip domain lookup
username cisco pri 15 password cisco
enable password cisco
line vty 0 4
  password cisco
  transport input all
interface G2
  no switchport
  ip add dhcp → then, static
write
```

Initial Config using GUI








2. Wireless Network Settings

Next



4. Summary
Finish

Trustpoint config & reboot after set up the mgmt. IP address of WLC

wireless config vwlc-ssc key-size 2048 signature-algo sha256 password 0 < pwd>
C9800#show wireless management trustpoint

Trustpoint Name: ewlc-default-tp

Certificate Info : Available Certificate Type : SSC

Certificate Hash: c4e57f728e523f64ade21597ab8ee472e7a7a8b7

Private key Info : Available FIPS suitability : Not Applicable

[*10/21/2019 17:30:17.7700] CAPWAP State: Discovery

[*10/21/2019 17:30:17.7730] Discovery Request sent to 192.168.30.200, discovery type STATIC_CONFIG(1)

[*10/21/2019 17:30:17.7770] Discovery Request sent to 192.168.30.200, discovery type STATIC_CONFIG(1)

[*10/21/2019 17:30:17.7790] Discovery Request sent to 255.255.255, discovery type UNKNOWN(0)

[*10/21/2019 17:30:17.7790] Discovery Response from 192.168.30.200 [*10/21/2019 17:30:17.7800] Discovery Response from 192.168.30.200

- [*10/21/2019 17:30:17.7810] Discovery Response from 192.168.30.200
- [*10/21/2019 17:30:26.0000]
- [*10/21/2019 17:30:26.0000] CAPWAP State: DTLS Setup
- [*10/21/2019 17:31:23.0150]
- [*10/21/2019 17:31:23.0150] CAPWAP State: DTLS Teardown
- [*10/21/2019 17:31:23.0260] Aborting image download(0x0): Dtls cleanup,
- [*10/21/2019 17:31:23.0850] do ABORT, part1 is active part
- [*10/21/2019 17:31:23.1000] upgrade.sh: Cleanup tmp files ...
- [*10/21/2019 17:31:27.7670] No more AP manager addresses remain..
- [*10/21/2019 17:31:27.7670] No valid AP manager found for controller 'c9800' (ip: 192.168.30.200)