


SDLE 10

ASSEMBLY MANUAL

装配说明书

螺丝说明

Screw specification



M3*8, d=M3, L=8

M5*40, d=M5, L=40



压柳螺母

swage nut



滚花螺母

knurled nut



偏心螺母

eccentric nut



自锁螺母

locknut



滑块螺母

Slider nut M5




T螺母

T nut

STEP 1

























M5 T nut

M5*8





















GT2





M3*8




M5*8


M5 T nut



























M5 T nut



M4 locknut



M4 swage nut



M4*30



M4*35



M5*8



M4*30



M4 swage nut



F624ZZ




M4 swage nut




M4 locknut













M4 * 35



M4 swage nut



F624ZZ



M4 swage nut



M4*6




M4 locknut




M4 gasket











E



E

E

F

E




F


G

H






E




F



E

F






SDLE 10

ASSEMBLY MANUAL

装配说明书

螺丝说明

Screw specification



M3*8, d=M3, L=8

M5*40, d=M5, L=40



压柳螺母

swage nut



滚花螺母

knurled nut



偏心螺母

eccentric nut



自锁螺母

locknut



滑块螺母

Slider nut M5



T螺母

T nut

STEP 2





M4*10









M4 swage nut

M4*35




M4 swage nut


M4*6


F624ZZ

















M4 locknut








M5 T nut M5*16





B

A

D

C








SDLE 10

ASSEMBLY MANUAL

装配说明书

螺丝说明

Screw specification



M3*8, d=M3, L=8

M5*40, d=M5, L=40



压柳螺母

swage nut



滚花螺母

knurled nut



偏心螺母

eccentric nut



自锁螺母

locknut



滑块螺母

Slider nut M5



T螺母


T nut

STEP 3






M4*30




M4*30



M5 gasket

M4*30





















M4*6









旋转偏心螺母，确保轮子能顺利滑动。




M4*10





M4 Slider nut















M5*8




M5 T nut






M5*10

M5*10







M3*12



M3 nut





M3 nut







M5*16





M5*25

















SDLE 10

ASSEMBLY MANUAL

装配说明书

螺丝说明

Screw specification



M3*8, d=M3, L=8

M5*40, d=M5, L=40



压柳螺母

swage nut



滚花螺母

knurled nut



偏心螺母

eccentric nut



自锁螺母

locknut



滑块螺母


Slider nut M5





T螺母


T nut


STEP 4






























M3 T nut


M3 gasket


M3*8












SDLE 10

ASSEMBLY MANUAL

装配说明书

螺丝说明

Screw specification



M3*8, d=M3, L=8

M5*40, d=M5, L=40



压柳螺母

swage nut



滚花螺母

knurled nut



偏心螺母

eccentric nut



自锁螺母

locknut



滑块螺母


Slider nut M5




T螺母

T nut

STEP 5








M3 T nut

M3 nut

plastic M3*6







舵机线的顺序一定不能插错，插错必烧

