

## **PRODUCT ERRATA**

PER#	2017001	PER ISSUE DATE	February 16 2017		
PER TITLE					
2017 Serial Numbers and FlyCapture Compatibility					
REVISION	2.0	CUSTOMER CONTACT	MV-Support@flir.com		
TYPE OF CHANGE					
☐ Electrical Specification ☐ Regulatory or Compliance   ☐ Mechanical Specification ☐ Part Number   ☐ Optical Specification ☐ End of Life   ☐ Firmware Specification ☒ Other					
SYMPTOMS					
Cameras do not enumerate in FlyCapture properly.					
OCCURRENCES					
All cameras with serial numbers 17XXXXXX or higher are affected.					
CAUSE					
Due to changes in our serial numbers, the GetCameraFromSerialNumber() FlyCapture API call will not properly find cameras in early releases. Any interface that supports FlyCapture1.X or Flycapture 2.X is affected. This would also affect all sample GUI applications such as FlyCap, DriverControlGUI, and UpdatorGUI as they initialize by serial number.					
RESOLUTION					
Upgrade to FlyCapture 2.11.3.60 (or later). This FlyCapture version does not have this issue.					
CUSTOMER ACTION REQUIRED					
Please see the following Knowledge Base article for details: https://www.ptgrey.com/KB/11106					

12051 Riverside Way, Richmond, BC, V6W 1K7 CANADA [T] 1.604.242.9937 | 1.866.765.0827 (toll free)

Document Number:	PER2017001
Revision Number:	2.0
Revision Date:	5-Jan-18
Document Availability:	Public