अध्यासिक ज्ञेंचा देवा वश्चयां कथा SUNRISE COMPUTER Technologies

ESTIMATE

SUNRISE COMPUTER TECHNOLOGY

Sales & Services | Thimphu : Bhutan

Mobile: +975 17835694 / 77835694 | Account No. (BoBL): 100917171 sunrisecomputer89@gmail.com | www.sunrisecomputech.com

No. 114 Bluston Post.					
Thimplui Bhuten					
Sl. No.	PARTICULARS	Qty.	Rate	Amount Nu.	Ch.
1)	Hp laserjet Pro P3015				
a)	Repuir duplen by Replacing duplon reverse	ţ	4000/-	400060	7
5)	Clatch & Forward Clatch				
3)	Replace Printer Port USB in Formater Board.	Ţ			
			Total	40004	5
(Ngultrums Four Thousand only). Signature					