E-WASTE RECOVERY USING HYDROMETALLURGY PROCESS DESCRIPTION & SUGGESTED MODIFICATIONS

Cost Reduction • Better Recovery • Higher Quality • Resource Efficiency

1. Purpose

This document focuses only on the hydrometallurgical recovery of valuable metals from e-waste. It describes the main process stages and practical modifications that can reduce processing cost, improve metal recovery and purity, and reduce water, chemical and energy consumption.

2. Hydrometallurgy for E-Waste Recovery

Hydrometallurgy is a metal-extraction method that uses aqueous chemical solutions to dissolve and recover valuable metals. For e-waste, it can be used to recover metals such as copper, nickel, gold, silver and other valuable elements, depending on the feed and selected chemistry.

3. Basic Five-Step Process

No.	Stage	Description
1	1. E-Waste Preparation	E-waste is collected, dismantled, sorted and size-reduced so that valuable metals become accessible to the leaching solution.
2	2. Leaching	A suitable aqueous leaching solution dissolves the target metal and transfers it from the solid material into a liquid solution.
3	3. Solution Purification	Impurities are removed and the target metal is selectively concentrated using methods such as precipitation, solvent extraction or ion exchange.
4	4. Metal Recovery	The target metal is recovered from the purified solution using precipitation, cementation, electrowinning or another suitable recovery method.
5	5. Refining / Final Quality Control	The recovered metal is further purified only when necessary to meet the required product specification.

Process flow: E-Waste Preparation → Leaching → Solution Purification → Metal Recovery → Refining / Final Quality Control

4. Suggested Modifications and Justification

Modification 1: Reduce Excessive Grinding

Suggested change: Instead of automatically grinding all e-waste to a very fine size, use sorting and only the particle size required for adequate metal liberation.

Justification: Fine grinding consumes significant electrical energy and causes equipment wear. If adequate metal exposure can be achieved at a coarser size, reducing grinding can lower electricity, maintenance and processing costs. Pre-sorting can also prevent unnecessary processing of unwanted material.

Limitation: The particle size must still be sufficient to achieve good metal recovery. Excessively coarse material may cause poor leaching.

Modification 2: Use Optimized or Heap Leaching Where Suitable

Suggested change: For suitable material, consider optimized leaching conditions or heap leaching instead of intensive tank-based processing.

Justification: Heap leaching can use simpler equipment and lower energy input than highly intensive processing. Optimizing leaching time, temperature, reagent concentration and solid-to-liquid ratio can also reduce chemical consumption while maintaining recovery.

Limitation: Heap leaching is slower and is not suitable for every type of e-waste. E-waste composition and physical characteristics must be evaluated first.

Modification 3: Use Selective Solution Purification

Suggested change: Use solvent extraction, ion exchange or selective precipitation according to the target metal and impurity chemistry.

Justification: E-waste leachates can contain several metals and impurities. A selective purification step can separate the desired metal more effectively, improving product purity and reducing unnecessary downstream treatment.

Limitation: The method must be selected according to solution chemistry, scale and economic feasibility.

Modification 4: Optimize Metal Recovery

Suggested change: Choose precipitation, cementation, electrowinning or another recovery method based on metal concentration, required purity, energy cost and recovery efficiency.

Justification: Different metals and solutions require different recovery methods. Selecting the appropriate method can improve recovery and product quality while controlling chemical and energy costs.

Limitation: No single recovery method is best for every metal or e-waste composition.

Modification 5: Minimize Separate Refining

Suggested change: Design purification and recovery stages so that the recovered metal reaches the required specification whenever technically possible.

Justification: Every additional refining stage requires equipment, energy, labour, maintenance and processing time. If the required purity is already achieved, unnecessary downstream refining can be reduced or avoided.

Limitation: Additional refining remains necessary when the recovered product does not meet the required purity.

5. Water and Chemical Recycling

An additional improvement is to recover and recycle process water and, where technically feasible, reuse or recover leaching reagents. This changes the process from a mainly one-way consumption model toward a more circular process.

- Reduces fresh-water requirement.
- Reduces consumption of chemical reagents.
- Reduces wastewater generation.
- Can lower wastewater-treatment and operating costs.
- Improves overall resource efficiency.

6. Real-Life Example: Copper Recovery

Copper hydrometallurgy demonstrates how purification and recovery can be integrated into an efficient process.

Leaching → Solvent Extraction (SX) → Electrowinning (EW) → Copper Cathode

In solvent extraction, copper is selectively transferred from the aqueous leach solution into an organic phase. The purified copper-bearing solution can then be processed by electrowinning, where electrical current deposits copper on a cathode. When the resulting copper already meets the required specification, a separate major refining stage may be reduced or avoided.

7. Cost and Quality Improvement Summary

Suggested Change	Cost Benefit	Quality / Recovery	Environmental Benefit
Reduce unnecessary grinding	Lower electricity and maintenance	Maintain recovery if liberation is adequate	Lower energy use
Optimize / use heap leaching where suitable	Potentially lower energy and equipment cost	Suitable recovery for appropriate feed	Potentially lower energy demand
Selective purification	Can reduce downstream treatment	Higher selectivity and purity	Less unwanted residue
Optimize metal recovery	Can reduce chemical/energy cost	Higher recovery and/or purity	Less metal lost in waste
Minimize separate refining	Avoids unnecessary processing	Required specification achieved earlier	Lower energy/material use
Recycle water and reagents	Lower fresh-water and reagent cost	More stable resource use when controlled	Less wastewater

8. Recommended Optimized Process

E-Waste Sorting / Size Reduction → Optimized Leaching → Selective Solution Purification → Efficient Metal Recovery → Minimum Necessary Refining → Water/Reagent Recycling

The purpose of the modification is not to remove stages without justification. It is to use the minimum processing intensity required to achieve the desired metal recovery and product quality at an acceptable cost.

9. Key Scientific Justification

The best hydrometallurgical process depends on e-waste composition, metal concentration, particle size, leaching behaviour, required product purity, recovery target, chemical price, energy cost, processing time and environmental requirements.

Therefore, the central improvement principle is: use the minimum particle size, leaching intensity, purification effort and refining required to achieve the desired recovery and product quality.

10. E-Waste Recovery Document – Signature

This section can be used for submission and faculty verification of the hydrometallurgical e-waste recovery process.

Student Name	Yash Redkar
Roll No. / PRN	24102B0011
Faculty / Guide Signature	
Date	25/8/2026