Part 2 - Description of Rehabilitation

Project: Ashby Mill, 410 Bridge Street, Danville, VA 24541 | NPS Project Number 47-2023-0318

Approval letter

August 22, 2023

Ashby Mill Owner LLC, c/o Riverside Heritage Development LLC

The National Park Service has reviewed the Part 2 application for the rehabilitation of the property named above. The proposed rehabilitation, if completed as described, will meet the Secretary of the Interior's Standards for Rehabilitation, subject to the conditions on page 3 of this decision.

Failure to meet the conditions may result in denial of certification of the completed work (Part 3). Approval of this application does not mean that the completed project will be certified.

NPS - CONDITIONALLY APPROVED
August 22, 2023
See conditions

Project summary

1. Proposed use: residential rental with ground-floor commercial space. The completed project will contain apartments on floors 1 to 5 and two commercial suites on the ground floor.
2. Estimated rehabilitation start: October 2023. Estimated completion: mid-2025.
3. The rehabilitation will be carried out as a single project, with the upper floors completed in sequence.
4. Architect: Hollins and Reade Architects, Richmond, Virginia.

Conditions of approval

Condition 1 The historic east stair shall be retained in place. Any new railings shall be simple in design and attached so that they can be removed later without damage.

Condition 2 Replacement windows must replicate the original wood profiles in material, dimensions and muntin pattern. Shop drawings for replacement windows must be submitted to and approved by NPS before installation.

Condition 3 Exposed timber columns and beams shall not be sandblasted or covered with new finishes.

Please send the information required by Condition 2 to the State Historic Preservation Office, which will forward it to the National Park Service.

Item 1 - Site work

Existing feature and condition: Regrade the area along the river elevation to drain away from the foundation. Existing granite curbing will be retained and reset.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 2 - Masonry

Existing feature and condition: Repoint deteriorated mortar joints with a lime-based mortar matched to the original in color, texture and strength. Replace spalled brick only where necessary, with brick matched in size and color.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 3 - Roof

Existing feature and condition: Replace the existing built-up roof with a new membrane roof. The stepped parapet will be repaired and capped. No rooftop additions will be visible from Bridge Street.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 4 - Windows

Existing feature and condition: The building has 412 historic window openings. Sash that can be repaired will be repaired. Sash too deteriorated to repair will be replaced with wood units replicating original profiles, as set out in the window survey.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 5 - Doors

Existing feature and condition: Original loading doors on the river elevation will be repaired and fixed in place, with new glazed doors set behind them.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 6 - Interior layout

Existing feature and condition: Upper floors will be divided into apartments. Corridors will follow the line of the central column bays so that the timber columns remain exposed.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 7 - Structure

Existing feature and condition: Timber columns and beams will be retained and cleaned with low-pressure methods. Damaged members will be sistered rather than removed.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 8 - Floors

Existing feature and condition: Maple flooring will be retained and refinished where it survives. New flooring in wet areas will be laid over the existing boards.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 9 - Stair tower

Existing feature and condition: The historic east stair will be retained in place as an exit stair, with code-required handrails added.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 10 - Mechanical systems

Existing feature and condition: New heating and cooling equipment will be placed on the roof behind the parapet and within apartment closets. Ductwork will run in corridors, not across exposed beams.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 11 - Electrical and lighting

Existing feature and condition: New wiring will be concealed in partition walls. Light fixtures in common areas will be simple and will not imitate historic fixtures.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 12 - Fire protection

Existing feature and condition: A new sprinkler system will be installed with exposed piping painted to match the ceiling.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 13 - Ground floor

Existing feature and condition: The ground floor will hold two commercial suites, the leasing office and residential amenities.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 14 - Boiler house

Existing feature and condition: The non-contributing boiler house will be stabilized and used for storage.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 1 - Site work (photographs and drawings)

Existing feature and condition: Regrade the area along the river elevation to drain away from the foundation. Existing granite curbing will be retained and reset.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 2 - Masonry (photographs and drawings)

Existing feature and condition: Repoint deteriorated mortar joints with a lime-based mortar matched to the original in color, texture and strength. Replace spalled brick only where necessary, with brick matched in size and color.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 3 - Roof (photographs and drawings)

Existing feature and condition: Replace the existing built-up roof with a new membrane roof. The stepped parapet will be repaired and capped. No rooftop additions will be visible from Bridge Street.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 4 - Windows (photographs and drawings)

Existing feature and condition: The building has 412 historic window openings. Sash that can be repaired will be repaired. Sash too deteriorated to repair will be replaced with wood units replicating original profiles, as set out in the window survey.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 5 - Doors (photographs and drawings)

Existing feature and condition: Original loading doors on the river elevation will be repaired and fixed in place, with new glazed doors set behind them.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 6 - Interior layout (photographs and drawings)

Existing feature and condition: Upper floors will be divided into apartments. Corridors will follow the line of the central column bays so that the timber columns remain exposed.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 7 - Structure (photographs and drawings)

Existing feature and condition: Timber columns and beams will be retained and cleaned with low-pressure methods. Damaged members will be sistered rather than removed.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 8 - Floors (photographs and drawings)

Existing feature and condition: Maple flooring will be retained and refinished where it survives. New flooring in wet areas will be laid over the existing boards.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 9 - Stair tower (photographs and drawings)

Existing feature and condition: The historic east stair will be retained in place as an exit stair, with code-required handrails added.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 10 - Mechanical systems (photographs and drawings)

Existing feature and condition: New heating and cooling equipment will be placed on the roof behind the parapet and within apartment closets. Ductwork will run in corridors, not across exposed beams.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 11 - Electrical and lighting (photographs and drawings)

Existing feature and condition: New wiring will be concealed in partition walls. Light fixtures in common areas will be simple and will not imitate historic fixtures.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 12 - Fire protection (photographs and drawings)

Existing feature and condition: A new sprinkler system will be installed with exposed piping painted to match the ceiling.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 13 - Ground floor (photographs and drawings)

Existing feature and condition: The ground floor will hold two commercial suites, the leasing office and residential amenities.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 14 - Boiler house (photographs and drawings)

Existing feature and condition: The non-contributing boiler house will be stabilized and used for storage.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 1 - Site work (photographs and drawings)

Existing feature and condition: Regrade the area along the river elevation to drain away from the foundation. Existing granite curbing will be retained and reset.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 2 - Masonry (photographs and drawings)

Existing feature and condition: Repoint deteriorated mortar joints with a lime-based mortar matched to the original in color, texture and strength. Replace spalled brick only where necessary, with brick matched in size and color.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 3 - Roof (photographs and drawings)

Existing feature and condition: Replace the existing built-up roof with a new membrane roof. The stepped parapet will be repaired and capped. No rooftop additions will be visible from Bridge Street.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 4 - Windows (photographs and drawings)

Existing feature and condition: The building has 412 historic window openings. Sash that can be repaired will be repaired. Sash too deteriorated to repair will be replaced with wood units replicating original profiles, as set out in the window survey.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 5 - Doors (photographs and drawings)

Existing feature and condition: Original loading doors on the river elevation will be repaired and fixed in place, with new glazed doors set behind them.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 6 - Interior layout (photographs and drawings)

Existing feature and condition: Upper floors will be divided into apartments. Corridors will follow the line of the central column bays so that the timber columns remain exposed.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 7 - Structure (photographs and drawings)

Existing feature and condition: Timber columns and beams will be retained and cleaned with low-pressure methods. Damaged members will be sistered rather than removed.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 8 - Floors (photographs and drawings)

Existing feature and condition: Maple flooring will be retained and refinished where it survives. New flooring in wet areas will be laid over the existing boards.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 9 - Stair tower (photographs and drawings)

Existing feature and condition: The historic east stair will be retained in place as an exit stair, with code-required handrails added.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 10 - Mechanical systems (photographs and drawings)

Existing feature and condition: New heating and cooling equipment will be placed on the roof behind the parapet and within apartment closets. Ductwork will run in corridors, not across exposed beams.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 11 - Electrical and lighting (photographs and drawings)

Existing feature and condition: New wiring will be concealed in partition walls. Light fixtures in common areas will be simple and will not imitate historic fixtures.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 12 - Fire protection (photographs and drawings)

Existing feature and condition: A new sprinkler system will be installed with exposed piping painted to match the ceiling.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 13 - Ground floor (photographs and drawings)

Existing feature and condition: The ground floor will hold two commercial suites, the leasing office and residential amenities.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.

Item 14 - Boiler house (photographs and drawings)

Existing feature and condition: The non-contributing boiler house will be stabilized and used for storage.

Proposed work and impact: the work will be carried out to the Standards and documented in the attached photographs and drawing sheets.