Part 2 - Description of Rehabilitation: Decision

August 14, 2023

Calder Works Owner LLC, c/o Halvorsen Urban Partners LLC. Project: Calder Shoe Company Works, 1200 Commerce Street, Lynchburg, VA 24504. NPS Project No. 51-2023-0447.

The National Park Service has reviewed the Description of Rehabilitation and has determined that the proposed rehabilitation will be consistent with the historic character of the property and the district, and will meet the Secretary of the Interior's Standards for Rehabilitation, only if the conditions set forth on page 4 of this decision are met. This determination does not constitute certification of the completed project, which may be denied if the conditions are not satisfied or if the work as completed departs from the work described.

NPS - APPROVED WITH CONDITIONS
August 14, 2023
Conditions: page 4

Project summary as represented by the applicant

1. Use after rehabilitation: residential rental apartments with resident amenity space on the ground floors.
2. Phasing: the applicant represents that Building A will be completed and occupied before work on Building B is completed.
3. Scope: rehabilitation of Buildings A and B. Building C, determined non-contributing in Part 1, is not included in the work reviewed under this application, and nothing in this decision should be read as a determination regarding work on Building C.
4. Architect of record: Moss & Varner Architects, Richmond, Virginia.

Item 5

Existing feature and condition: Masonry: repoint with lime-based mortar matched to the original in color, texture and compressive strength; replace spalled brick in kind.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Conditions of approval

Condition 1 The fired-clay (terra cotta) cornice and frieze on the Commerce Street elevation of Building A are character-defining features. They must be retained and repaired in situ. Replacement of individual units may be undertaken only where a unit is documented in the conditions survey as deteriorated beyond repair, and then only in kind, matching the original in material, color, profile and finish. The use of substitute materials, including glass-fiber-reinforced concrete, fiberglass or cast stone, has not been reviewed and is not approved.

Condition 2 The central light court of Building B is a character-defining feature and shall remain open to the roof for its full height. No new floor plates or infill within the light court are approved. The applicant shall submit, as an amendment to this application, revised floor plans reflecting the resulting reduction in the number of dwelling units.

Any proposal affecting the work described in Conditions 1 and 2 must be submitted to the State Historic Preservation Office as an amendment for review by the National Park Service before the work is undertaken.

Item 6

Existing feature and condition: Windows: repair existing steel sash; replace only units documented as deteriorated, with steel units of matching profile and sightlines.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 7

Existing feature and condition: Roof: new membrane roof set behind parapets; no visible rooftop additions from Commerce Street.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 8

Existing feature and condition: Interior: retain concrete columns and mushroom capitals exposed in corridors and units.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 9

Existing feature and condition: Light court (Building B): retain open to roof per Condition 2.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 10

Existing feature and condition: Cornice (Building A): retain and repair per Condition 1.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 11

Existing feature and condition: Mechanical: rooftop equipment set back a minimum of fifteen feet from street elevations.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 12

Existing feature and condition: Stairs: retain historic stair towers; add code-compliant guards designed to be reversible.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 13

Existing feature and condition: Masonry: repoint with lime-based mortar matched to the original in color, texture and compressive strength; replace spalled brick in kind.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 14

Existing feature and condition: Windows: repair existing steel sash; replace only units documented as deteriorated, with steel units of matching profile and sightlines.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 15

Existing feature and condition: Roof: new membrane roof set behind parapets; no visible rooftop additions from Commerce Street.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 16

Existing feature and condition: Interior: retain concrete columns and mushroom capitals exposed in corridors and units.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 17

Existing feature and condition: Light court (Building B): retain open to roof per Condition 2.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 18

Existing feature and condition: Cornice (Building A): retain and repair per Condition 1.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 19

Existing feature and condition: Mechanical: rooftop equipment set back a minimum of fifteen feet from street elevations.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 20

Existing feature and condition: Stairs: retain historic stair towers; add code-compliant guards designed to be reversible.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 21

Existing feature and condition: Masonry: repoint with lime-based mortar matched to the original in color, texture and compressive strength; replace spalled brick in kind.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 22

Existing feature and condition: Windows: repair existing steel sash; replace only units documented as deteriorated, with steel units of matching profile and sightlines.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 23

Existing feature and condition: Roof: new membrane roof set behind parapets; no visible rooftop additions from Commerce Street.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 24

Existing feature and condition: Interior: retain concrete columns and mushroom capitals exposed in corridors and units.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 25

Existing feature and condition: Light court (Building B): retain open to roof per Condition 2.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 26

Existing feature and condition: Cornice (Building A): retain and repair per Condition 1.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 27

Existing feature and condition: Mechanical: rooftop equipment set back a minimum of fifteen feet from street elevations.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 28

Existing feature and condition: Stairs: retain historic stair towers; add code-compliant guards designed to be reversible.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 29

Existing feature and condition: Masonry: repoint with lime-based mortar matched to the original in color, texture and compressive strength; replace spalled brick in kind.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 30

Existing feature and condition: Windows: repair existing steel sash; replace only units documented as deteriorated, with steel units of matching profile and sightlines.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.

Item 31

Existing feature and condition: Roof: new membrane roof set behind parapets; no visible rooftop additions from Commerce Street.

Proposed work and impact on the feature: the work will be undertaken in accordance with the Standards and the drawings and photographs referenced for this item.