

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	1999-12
Local Time Of Day	1801-2400

PLACE

Locale Reference	Airport
Locale	ZZZ.Airport
State	US
Relative Position - Distance Nautical Miles	0
Altitude - AGL	200

ENVIRONMENT

Flight Conditions	VMC
Light	Night

AIRCRAFT / EQUIPMENT X

ATC / Advisory - Tower	ZZZ.Tower
Aircraft Operator	Air Carrier
Make Model Name	B737-300
Crew Size	2
Operating Under FAR Part	Part 121
Flight Plan	IFR
Mission	Passenger
Nav In Use	FMS Or FMC
Flight Phase	Takeoff / Launch
Flight Phase	Initial Climb
Airspace - Class B	ZZZ.B
Number Of Seats	137

AIRCRAFT / EQUIPMENT Y

ATC / Advisory - Tower	ZZZ.Tower
Aircraft Operator	Air Carrier
Make Model Name	B737 Undifferentiated or Other Model
Crew Size	2
Operating Under FAR Part	Part 121
Flight Plan	IFR
Mission	Passenger
Flight Phase	Taxi

PERSON 1

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Crew	Captain
Function - Flight Crew	Pilot Flying
Qualification - Flight Crew	Air Transport Pilot (ATP)
Qualification - Flight Crew	Multiengine
Experience - Flight Crew Total	10000 hrs
Experience - Flight Crew Last 90 Days	250 hrs
Experience - Flight Crew Type	250 hrs
ASRS Report Number	456663
Callback	Completed

PERSON 2

Aircraft Reference	X
Reporter Organization	Air Carrier
Function - Flight Crew	First Officer
Function - Flight Crew	Pilot Not Flying
Qualification - Flight Crew	Air Transport Pilot (ATP)

PERSON 3

Aircraft Reference	Y
Reporter Organization	Air Carrier
Function - Flight Crew	Captain

Function - Flight Crew
Qualification - Flight Crew

Pilot Flying
Air Transport Pilot (ATP)

PERSON 4

Location Of Person ZZZ.Tower
Reporter Organization Government
Function - Air Traffic Control Local
Qualification - Air Traffic Control Fully Certified

PERSON 5

Location Of Person ZZZ.Tower
Reporter Organization Government
Function - Air Traffic Control Ground
Qualification - Air Traffic Control Fully Certified

EVENTS

Anomaly ATC Issue - All Types
Anomaly Conflict - Ground Conflict, Critical
Anomaly Ground Event / Encounter - Other / Unknown
Detector - Person Flight Crew
Miss Distance - Horizontal 0
Miss Distance - Vertical 200
Result - Flight Crew Took Evasive Action

ASSESSMENTS

Contributing Factors / Situations Human Factors
Primary Problem Human Factors

NARRATIVE 1

MY ACFT WAS CLRED FOR TKOF ON CTR RWY AND A R TURN TO 090 DEGS. WE ARE CONFIGURED FOR A BLEEDS OFF FLAPS 5 DEG TKOF. AS WE ARE ACCELERATING THROUGH 120 KTS, WE SEE ACFT OF RECIPROCAL CTR RWY. WE ARE NOW PAST ABORT SPD AND SELECT MAX PWR AND ROTATE EARLY. I CLB OUT JUST ABOVE THE STICK SHAKER (ON THE HUD) AND EASE L. WE FLY ABOVE AND TO THE L OF THE ACFT CLRING THE RWY. I GAIN ENOUGH ALT FOR OBSTACLE CLRNC AND LET THE ACFT SLICE L, BECAUSE OUR ANGLE OF ATTACK IS SO HIGH AND I ALREADY HAVE SOME L BANK IN DUE TO CLRING AWAY FROM

THE INTRUDING ACFT. AS I REGAIN FLYING AIRSPD, ZZZ TWR RADIOS NOT TO WORRY ABOUT TURNING R BUT TO CONTINUE L TO 090 DEGS. REMAINDER OF FLT WAS UNEVENTFUL. DURING POSTFLT WALKAROUND WE DISCOVER A SMALL PAINT SCRAPE (NO SKIN DAMAGE) UNDER THE TAIL. LATER INFO REVEALED SIMILAR CALL SIGNS. WE WERE ACR ABB, THEY WERE SAME ACR CBB. WE NEVER HEARD ACR CBB RESPOND AND NEITHER DID TWR. I BELIEVE THEIR CALL MAY HAVE BEEN BLOCKED BY OUR RESPONSE. CALLBACK CONVERSATION WITH RPTR REVEALED THE FOLLOWING INFO: CREW WAS FLYING A B737-300 ACFT. THE ACR HAS EQUIPPED THEIR ACFT WITH A HUD. THE CAPT HAD PREVIOUS MIL EXPERIENCE USING HUDS SO IT WAS NATURAL TO UTILIZE THE HUD IN THE AVOIDANCE MANEUVER. THE CAPT HAS BRIEFED THE COMPANY CHIEF PLT AND THE FAA HAS INITIATED AN INVESTIGATION. THE CAPT ESTIMATED THEY MISSED THE OTHER ACFT BY ABOUT 200 FT. HE RECEIVED EXTENSIVE TRAINING IN OP OF THE HUD IN THE ACR'S SIMULATOR AND CREDITS IT FOR BEING ABLE TO FLY A PRECISE MAX EFFORT CLB. THE CAPT THINKS THE FAA SHOULD REQUIRE ALL ACR ACFT TO BE EQUIPPED WITH HUDS.

SYNOPSIS

B737 CREW HAD ANOTHER B737 ACFT NOSE TO NOSE WITH THEM ON TKOF.

