

REPORT CLASSIFICATION

Classification Type	Full Form Analysis
---------------------	--------------------

DATE / TIME

Date of Occurrence	2008-11
Local Time Of Day	1201-1800

PLACE

Locale Reference	Airport
Locale	ZZZ.Airport
State	US
Altitude - AGL	0

AIRCRAFT / EQUIPMENT X

Aircraft Operator	Air Carrier
Make Model Name	B737-900
Operating Under FAR Part	Part 121
Mission	Passenger
Flight Phase	Parked

COMPONENT 1

Aircraft Reference	X
Aircraft Component	Cargo Door

PERSON 1

Location Of Person	Company
Reporter Organization	Air Carrier
Function - Maintenance	Technician
Qualification - Maintenance	Airframe
Qualification - Maintenance	Powerplant
Experience - Maintenance Technician	6 yrs
ASRS Report Number	812857
Callback	Completed

EVENTS

Anomaly	Aircraft Equipment Problem - Less Severe
Anomaly	Deviation / Discrepancy - Procedural - FAR
Anomaly	Deviation / Discrepancy - Procedural - Published Material / Policy
Detector - Person	Other Person
Result - General	Maintenance Action
Result - General	None Reported / Taken

ASSESSMENTS

Contributing Factors / Situations	Aircraft
Contributing Factors / Situations	Human Factors
Contributing Factors / Situations	Logbook Entry
Primary Problem	Human Factors

NARRATIVE 1

ON ACFT X I WAS CALLED OUT TO LOOK AT A FORWARD CARGO DOOR FOR DENTS. MY MEASURES WERE 1.1 INCH BY 2.5 INCHES BY .040 INCH DEEP. PER THE SRM, MY WIDTH/DEPTH MUST BE 30 OR MORE. I USED THE WRONG MEASUREMENT IN MY FORMULA. (I USED 2.5 INCHES/.040=62.5) MY FORMULA SHOULD HAVE BEEN 1.1 FEET/.040=27. I PLACED THE DENT ON MAINT HISTORY RATHER THAN DEFERRED ITEM REF SRM ALLOWABLE DAMAGE SECTION. I HAVE ALREADY CLOSED THE MAINT HISTORY AND OPENED THE CORRECT DEFERRED ITEM IN REF WITH SRM ALLOWABLE DAMAGE SECTION. NEW GENERAL SRM WITH MAX WIDTH VERSUS CLASSIC MINOR AXIS. JUST USED THE WRONG MEASURE. CALLBACK CONVERSATION WITH RPTR REVEALED THE FOLLOWING INFO: REPORTER STATED THE NEXT GEN B737-700/800/900 STRUCTURAL REPAIR MANUAL (SRM) USES THE LETTER 'W', MEANING WIDTH, FOR THE DAMAGE CRITERIA FORMULA W/Y, TO DETERMINE IF THE AIRCRAFT DAMAGE REQUIRES IMMEDIATE REPAIR, OR CAN BE DEFERRED UNDER CERTAIN CATEGORIES. THE 'Y' FACTOR REPRESENTS THE DEPTH OF THE DENT. REPORTER STATED THE CLASSIC B737-300/400/500 SRM'S CONTINUE TO USE THE LETTER 'A' FOR THE WIDTH FORMULA WHEN DETERMINING THEIR A/Y DAMAGE CRITERIA. HE JUST USED THE LENGTH MEASUREMENT, INSTEAD OF THE WIDTH, FOR THE DAMAGE CALCULATIONS.

SYNOPSIS

MECHANIC CALLED OUT TO LOOK AT A FORWARD CARGO DOOR FOR DENTS ON B737-900 AIRCRAFT, USED THE LENGTH MEASUREMENT INSTEAD OF THE WIDTH MEASUREMENT, WHEN HE APPLIED THE W/Y FORMULA IN THE SRM FOR DETERMINING ALLOWABLE

DAMAGE.

