




HOW TO ORDER
30COB-1818-L 8RA

DIMENSIONS	
CD	= .0001 ± .0001 [0.003 ± 0.001]
ERL	= .0064 [0.163] (REF)
FD	= .0040 ± .0008 [0.102 ± 0.019]
FL	= .0030 ± .0002 [0.076 ± 0.005]
FRO	= .0011 [0.028] (REF)
H	= .0018 ± .0002 [0.046 ± 0.005]
T	= .0140 ± .0005 [0.356 ± 0.013]
TD	= .0624 ± .0001 [1.585 ± 0.003]
TDF	= .0460 ± .0005 [1.168 ± 0.013]
TL	= .8280 ± .0050 [21.031 ± 0.127]

MATERIAL	DRAWN				SECTION AF-AF			
TREATMENT	3/6/2026				SCALE 10:1			
UNLESS OTHERWISE SPECIFIED INCH [mm] .XX = ± .01 [0.25] .XXX = ± .005 [0.127] .XXXX = ± .0005 [0.0127] FRACTIONS = ± 1/64 [0.40] ANGLE = ± 1° FINISH: ALL SURFACES ✓ 8/ MAX	CKD.	DATE	 small precision tools		TITLE 3112256TF			
	ENG.	DATE						
	MKTG.	DATE						
	PROD.	DATE						
	3rd ANGLE PROJECTION		SCALE 8;8;8	DWG A	DRAWN_BY WAD.Runner	REV. A		
ACAD FILE #:		3112256		SUPERS.				