







DIMENSIONS		
CD	=	.0002 ±.0001 [0.004 ±0.001]
ERL	=	.0084 [0.213] (REF)
FD	=	.0034 ±.0008 [0.086 ±0.019]
FL	=	.0025 ±.0002 [0.064 ±0.005]
FRO	=	.0009 [0.023] (REF)
H	=	.0018 ±.0002 [0.046 ±0.005]
T	=	.0140 ±.0005 [0.356 ±0.013]
TD	=	.0624 ±.0001 [1.585 ±0.003]
TDF	=	.0460 ±.0005 [1.168 ±0.013]
TL	=	.8260 ±.0050 [21.031 ±0.127]

HOW TO ORDER
30COB-1818-L

MATERIAL		DRAWN		SECTION AF-AF	
TREATMENT		3/2/2026		SCALE 10:1	
UNLESS OTHERWISE SPECIFIED INCH [mm] .XX = ± .01 [0.25] .XXX = ± .005 [0.127] .XXXX = ± .0005 [0.0127] FRACTIONS = ± 1/64 [0.40] ANGLE = ± 1° FINISH: ALL SURFACES ✓ ⁸ MAX		CKD.	DATE	 small precision tools	
		ENG.	DATE		
		MKTG.	DATE		
		PROD.	DATE	TITLE	
3rd ANGLE PROJECTION		SCALE	DWG	DRAWN_BY	REV.
8/		8;8;8	A	WAD.Runner	A
FINISH: ALL SURFACES ✓ ⁸ MAX		ACAD FILE #:		SUPERS.	
		3112255			