





HOW TO ORDER
30COB-1515-L (RF) W=003 T=011 8RA BR=0006
2024720

DIMENSIONS	
CD=	.0001 ±.0000 [0.003 ±0.001]
ERL=	.0055 [0.14] (REF)
FD=	.0030 ±.0008 [0.076 ±0.019]
FL=	.0021 ±.0002 [0.054 ±0.005]
FRO=	.0010 ±.0001 [0.025 ±0.003]
H=	.0015 ±.0002 [0.038 ±0.005]
T=	.0110 ±.0005 [0.279 ±0.013]
TD=	.0624 ±.0001 [1.585 ±0.003]
TDF=	.0460 ±.0005 [1.168 ±0.013]
TL=	.8280 ±.0050 [21.031 ±0.127]

MATERIAL	DRAWN 3/3/2026		SECTION A-A SCALE 10:1		
TREATMENT	CKD.	DATE	SPT small precision tools		
UNLESS OTHERWISE SPECIFIED INCH [mm] .XX = ± .01 [0.25] .XXX = ± .005 [0.127] .XXXX = ± .0005 [0.0127] FRACTIONS = ± 1/64 [0.40] ANGLE = ± 1° FINISH: ALL SURFACES ✓ 8 MAX	ENG.	DATE			
	MKTG.	DATE			
	PROD.	DATE			
	3rd ANGLE PROJECTION		SCALE 8;8;8	DWG A	DRAWN_BY WAD.Runner
		ACAD FILE #: 3131804		SUPERS.	