RGB calibration: 9 x 6 inner corners; square 20 mm



Origin: first INNER corner above/right of lower-left outer square. Verify corner 0 overlay.

Print at 100% / actual size. Measure the printed square. Board coordinates: +X right, +Y up.