
01 / START HERE

Sign in as a reviewer

Use the sample accounts to explore both sides of the repair workflow. The guide is also available from the login screen at https://pave-pulse.vercel.app/reviewer-guide.pdf.



Illustrative interface screenshot; live values may differ.

1. Open the live prototype. Visit https://pave-pulse.vercel.app/. On the login page, select a demo account to fill the username and password, then click Sign in.

ENGINEER

Username: engineer
Password: engineer123

WORKER

Username: worker
Password: worker123


2. Choose the role that matches the steps you want to try. Engineer can view the map, review incidents, dispatch repairs, view devices and manage team access. Worker sees only work orders assigned to them and updates repair progress.

Prototype-only accounts: These passwords are intentionally simple and visible to reviewers. Do not enter personal information or real municipal data.

02 / ENGINEER

Explore the Pune dashboard

The map, filters, overview counts and repair verification queue are the starting point for the Engineer workflow.



Illustrative interface screenshot; live values may differ.

1. Read the overview cards. The KPI cards summarize incidents and repair status. Because this is a prototype, the exact totals depend on the demo seed and any actions other reviewers have taken.


2. Filter the map. Use the filters above the map to narrow incidents by zone, route, status, severity or date. Click a colored marker to open its incident details. Use the map zoom controls to inspect a cluster.

3. Interpret locations carefully. The data uses illustrative coordinates around Pune localities such as Baner, Aundh, Shivajinagar, Kothrud, Kharadi and Hadapsar. These are not surveyed road defects or official PMC records.

03 / ENGINEER

Review and dispatch a repair

A work order should be created only after an Engineer reviews the incident.



Illustrative interface screenshot; live values may differ.

1. Open an incident. Click a map marker and review its severity, coordinates, reporting timestamp, clustered reports, zone and current status.

2. Mark it as reviewed. Click Mark defect as reviewed. Once the incident is in review, the dispatch action becomes available.


3. Dispatch. Click Create & dispatch work order. The API creates a ticket and synchronizes the incident status. Then open Work orders to inspect the ticket.

4. Try the duplicate workflow. If the interface lists nearby same-severity candidate reports, review the locations before merging. For this demo, do not interpret synthetic incidents as verified real-world defects.

04 / WORKER

Complete an assigned work order

The Worker view is intentionally narrower than the Engineer view.



Illustrative interface screenshot; live values may differ.

1. Sign out of Engineer and sign in as Worker. The Worker landing page opens directly on Work orders and should list only jobs assigned to that account.

2. Start the job. Open an assigned ticket and set its status to In progress. Add a clear completion note describing the demonstration repair.


3. Add evidence. Upload an illustrative JPG/PNG image or PDF where the interface allows evidence upload. Keep files small; the API enforces a 5 MB limit. Never upload private, sensitive or identifiable information to the public demo.

4. Complete the task. Mark the work order resolved. A completion note or evidence is required. The linked incident moves to the independent repair-verification queue.

05 / VERIFY & FINISH

Check repair verification and support screens

Use this final pass to show how a completed ticket is tracked after field work.



Illustrative interface screenshot; live values may differ.

Repair verification. A resolved work order appears in Awaiting verification. The demo requires two distinct buses to report a clear surface within the configured radius. Repeat passes from one bus do not count as independent verification. A new defect can reopen the incident.

Devices. Engineers can review the registered device health fields, including connectivity, last message and software version. In this prototype, do not expect actual hardware telemetry unless a device integration is configured.

Team access. Engineers can review or disable operational accounts when this feature is enabled. Do not create extra reviewer accounts unless the test requires it.

Quick troubleshooting: If the first login is slow, Render may be waking the free API from idle. Wait up to about a minute and retry. If login fails repeatedly, contact the project owner instead of changing the database or credentials.