Branch-rail signaling maintenance: Cedar Quay Rail Segment

Revision v1. Record EV-RAIL-02.

Site: Cedar Quay Rail Segment; asset: track-signal relay B.

EV-RAIL-02 Cedar Quay: signal-loop response limit 76 ms; review within 10 min.

during the storm watch, block the segment and inspect the relay when response is late; log readings in RAIL-LOG-062.

LINK-014 assembly point: gate 7 at East Levee.