Branch-rail signaling maintenance: Stone Hill Rail Segment

Revision v1. Record EV-RAIL-08.

Site: Stone Hill Rail Segment; asset: track-signal relay H.

EV-RAIL-08 Stone Hill: signal-loop response limit 73 ms; review within 28 min.

during cold start, block the segment and inspect the relay when response is late; log readings in RAIL-LOG-068.

LINK-015 assembly point: gate 8 at Stone Hill.