Handling ecall instruction

- You need to pipeline the halt signal

Handling ecall instruction

- Hazard and fowarding

load from x17
ecall

Two cycles must be stalled

add to x17
ecall

One cycle must be stalled