

Machine Incident Report

Machine: Boiler-1

Date: 31-07-2026

Issue:

Machine temperature reached 120°C.

Pressure increased to 160 PSI.

Cooling fan stopped working.

High vibration detected.

Observation:

Possible overheating due to cooling system failure.

Recommendation:

Inspect cooling fan.

Check coolant level.

Reduce machine load.