

Traveo™ II Family AUTOSAR MCAL MAKE Release Notes

SRN223358 Version 1.3

About this document

Scope and purpose

Thank you for your interest in the Traveo II Family AUTOSAR MCAL MAKE Driver version 1.3. This document lists the installation requirements, software changes, limitations, and known issues.

Intended audience

This document is intended for anyone who uses the MAKE driver of the Traveo II family.

Table of contents

About this document	1
Table of contents	1
1 System Requirements and Recommendations	2
1.1 Supported Compilers	2
1.2 Compiler Options	2
1.3 Library Compiler Options	3
1.4 Memory Consumption	4
1.5 Stack Consumption	4
1.6 Release Details	4
2 Installation	5
3 Deviations from AUTOSAR	6
4 Limitations	7
5 Known Defects	8
6 Documentation	9
7 Technical Support	10
8 Version History	11
8.1 Module SW-Version 1.0	11
8.2 Module SW-Version 1.1	11
8.3 Module SW-Version 1.2	11
8.4 Module SW-Version 1.3	11

System Requirements and Recommendations

1 System Requirements and Recommendations

Software Prerequisites	Supported Version
EB tresos Studio Package for Cypress	26.2.0

1.1 Supported Compilers

Green Hills Software, Compiler v2017.1.4

IAR Embedded Workbench 8.0, EWARM FS 8.22.3

1.2 Compiler Options

This section summarizes the compiler options used to build and test the module. When changing the compiler options, the module must be considered untested.

Compiler	Option (Cortex®-M4F Core)
Green Hills Software, Compiler v2017.1.4	-cpu=cortexm4f -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fsingle

Compiler	Option (Cortex-M7 Core)
Green Hills Software, Compiler v2017.1.4	-cpu=cortexm7 -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fhard

Compiler	Option (Cortex-M0+ Core)
Green Hills Software, Compiler v2017.1.4	-cpu=cortexm0plus -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fsoft

Compiler	Option (Cortex-M4F Core)
IAR Embedded Workbench 8.0, EWARM FS 8.22.3	--debug --endian=little --cpu=Cortex-M4 -e --fpu=VFPv4_sp -Ohs --no_size_constraints

System Requirements and Recommendations

Compiler	Option (Cortex-M7 Core)
IAR Embedded Workbench 8.0, EWARM FS 8.22.3	--debug --endian=little --cpu=Cortex-M7 -e --fpu=VFPv5_d16 -Ohs --no_size_constraints

Compiler	Option (Cortex-M0+ Core)
IAR Embedded Workbench 8.0, EWARM FS 8.22.3	--debug --endian=little --cpu=Cortex-M0+ -e -Ohs --no_size_constraints

1.3 Library Compiler Options

If a binary library has been delivered with this module, it has been built using the following options:

Compiler	Option (Cortex-M4F Core)
Green Hills Software, Compiler v2017.1.4	-cpu=cortexm4f -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fsingle

Compiler	Option (Cortex-M7 Core)
Green Hills Software, Compiler v2017.1.4	-cpu=cortexm7 -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fhard

Compiler	Option (Cortex-M0+ Core)
Green Hills Software, Compiler v2017.1.4	-cpu=cortexm0plus -thumb -thumb_lib -C99 --short_enum -align4 --no_commons --no_alternative_tokens -asm3g -preprocess_assembly_files -nostartfiles -globalcheck=normal -globalcheck_qualifiers --prototype_errors -Wformat -Wimplicit-int -Wshadow -Wtrigraphs -Wundef -reject_duplicates -c -list -Ospeed -OI -Olink -Ointerproc -Omax -fsoft

Compiler	Option (Cortex-M4F Core)
IAR Embedded Workbench 8.0, EWARM FS 8.22.3	--debug --endian=little --cpu=Cortex-M4 -e --fpu=VFPv4_sp -Ohs --no_size_constraints

System Requirements and Recommendations

Compiler	Option (Cortex-M7 Core)
IAR Embedded Workbench 8.0, EWARM FS 8.22.3	--debug --endian=little --cpu=Cortex-M7 -e --fpu=VFPv5_d16 -Ohs --no_size_constraints

Compiler	Option (Cortex-M0+ Core)
IAR Embedded Workbench 8.0, EWARM FS 8.22.3	--debug --endian=little --cpu=Cortex-M0+ -e -Ohs --no_size_constraints

1.4 Memory Consumption

The Make plugin does not consume memory.

1.5 Stack Consumption

The Make plugin does not consume stack.

1.6 Release Details

Module Software Version
1.3.x (x=software patch version; see the delivery notes for details)

AUTOSAR Specification Version (ASR)
4.2.2

Target
MXS40

MCAL Configuration Settings	Supported Derivatives
See the Resource Release Notes	See the Resource Release Notes

Installation

2 Installation

See the Installation Manual for EB tresos Studio for CYPRESS AUTOSAR Software Products and Installation Manual for MCAL42-Traveo.

3 Deviations from AUTOSAR

This release has no deviations.

Limitations

4 Limitations

This release has no limitations.

Known Defects

5 Known Defects

The listed issues were known at the day this release note was generated. Further problems may have been discovered in the meantime. For an up-to-date list of known issues, contact your Cypress sales representative.

This release has no known issues at the time of release.

6 Documentation

All User Guides for MCAL drivers are in the `\doc` subdirectory of the *installation* directory. The default location is:

C:\CYPRESS_ESDB\Tresos26_2_0\doc

7 Technical Support

If you have questions related to the driver, contact the local support application engineer.

Version History

8 Version History

8.1 Module SW-Version 1.0

Initial module setup.

8.2 Module SW-Version 1.1

T2MC-38111 - Base module in conflict with EB Base module

Title: Base module in conflict with EB Base module

Description: Base module delivered by Cypress is containing files in conflict with the Base module delivered by EB.

Cypress Base module follows these rules:

- Keep the standard files in Base module
- Move controller/compiler specific headers in Platform plugin

This could be achieved with moving files from CYT2 folder into Platform Cypress plugin.

8.3 Module SW-Version 1.2

T2MC-55803 - Rename target CYT2 to MXS40

Title: Rename target CYT2 to MXS40

Description: The target name should be renamed from CYT2 to MXS40.
Target name MXS40 can be used as unified name for TraveoII family.

8.4 Module SW-Version 1.3

T2MC-77594 - Support IAR Compiler

Title: Support IAR Compiler

Description: Support IAR Compiler (IAR EWARM FS 8.22.3.15992).

Following is supported in release V1.5.0.

T2MC-39519 - Support EB tresos V26.2.0

Title: Support EB tresos V26.2.0

Description: Support EB tresos V26.2.0
[Impact]

Strict AUTOSAR specification and check for parameter configuration errors are implemented in EB tresos V26.2.0.

Version History

In addition, handling of reference paths (relative paths) such as System Description file (ARXML) is changed in EB tresos V26.2.0.

Therefore, if the current ECUC Configuration Definitions XML file contains deviations or errors, you may find errors during import to tresos26. In that case, the ECUC Configuration Definitions XML file must be modified appropriately.

In addition, if the current ARXML file contains unresolvable paths, you may find errors during import to tresos26. In that case, ARXML file must be modified.

The SW has been tested in Cypress; no risks except for the low-level risk listed above were found.

Trademarks

All referenced product or service names and trademarks are the property of their respective owners.

Edition 2020-11-19

Published by

Infineon Technologies AG

81726 Munich, Germany

© 2018-2020 Infineon Technologies AG.

All Rights Reserved.

Do you have a question about this document?

Go to www.cypress.com/support

Document reference

002-23358 Rev. *D

IMPORTANT NOTICE

The information contained in this application note is given as a hint for the implementation of the product only and shall in no event be regarded as a description or warranty of a certain functionality, condition or quality of the product. Before implementation of the product, the recipient of this application note must verify any function and other technical information given herein in the real application. Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind (including without limitation warranties of non-infringement of intellectual property rights of any third party) with respect to any and all information given in this application note.

The data contained in this document is exclusively intended for technically trained staff. It is the responsibility of customer's technical departments to evaluate the suitability of the product for the intended application and the completeness of the product information given in this document with respect to such application.

For further information on the product, technology delivery terms and conditions and prices please contact your nearest Infineon Technologies office (www.infineon.com).

WARNINGS

Due to technical requirements products may contain dangerous substances. For information on the types in question please contact your nearest Infineon Technologies office.

Except as otherwise explicitly approved by Infineon Technologies in a written document signed by authorized representatives of Infineon Technologies, Infineon Technologies' products may not be used in any applications where a failure of the product or any consequences of the use thereof can reasonably be expected to result in personal injury.