WHITE / BLACK sensor calibration

Print 100%. Use same paper, ink, height and lighting as the map.

WHITE: centre inside frame



BLACK: centre inside patch



Measure this scale: 100 mm

Keep all five probes inside one target; normal ground clearance.

Do not use lifted-wheel geometry for ground-operation calibration.