

Type	Low-frequency start	Origin detour image	What to watch
type 0	finite point on real axis	no extra large arc	whether the curve surrounds $(-1, 0)$
type I	$ G(j0)H(j0) \rightarrow \infty$	one 90° turn after completing the small contour	crossing direction near the negative real axis
type II	stronger singularity at the origin	larger turn, easier to swing to the left of -1	full-loop direction can change even when $P = 0$
type III and above	curve starts from infinity with more severe phase lag	multiple 90° turns accumulated	unstable examples appear even without RHP open-loop poles