

Rule

$$N = P/2$$

$$Z = P - 2N$$

count only $(-\infty, -1)$

half crossing allowed

detour around

imaginary-axis poles

if $Z < 0$

Meaning

half Nyquist curve gives a stable closed loop

number of unstable closed-loop poles

other real-axis intersections do not matter

start/end on $(-\infty, -1)$ counts as ± 0.5

the small contour in the s plane becomes a large arc in the image plane

the sign or crossing count is wrong; recompute the direction