

Observed problem

good transient, large
steady-state error

small steady-state error,
poor dynamics

both steady-state and tran-
sient are unsatisfactory

Frequency-domain action

increase low-frequency gain, keep mid/high frequency al-
most unchanged

modify mid/high frequency to change ω_c and phase mar-
gin

low / mid / high frequency bands all need redesign