MD1.3 2A Dual Motor Controller SKU DRI0002



MD1.3 2A Dual Motor Controller (SKU: DRI0002)


Introduction

This is a 4.8-46V, 2A Dual Motor Controller which is the revised version of the DF-MDV1.0. Its performance has been improved greatly. It can bear larger current due to the increased haetsink dissipation. It is easy to control, using LGS's outstanding high-power motor driver chip, the L298N. This chip allows for direct drive of two bi-directional DC motors, and incorporates high-speed short diodes for protection. Drive current up to 2A per motor output. The driver uses a broad-brush design to reduce wire resistance.

Specifications

- The logic part of the input voltage: 6 ~ 12V
- Driven part of the input voltage Vs: 4.8 ~ 46V
- · The logical part of the work current lss: 36mA
- Drive part of the operating current lo: 2A
- Maximum power dissipation: 25W (T = 75 degree Celsius)
- Control signal input level:
- High level: 2.3V = Vin = Vss
- Low:-0.3V = Vin = 1.5V
- Operating temperature: -25 degree Celsius ~ +130 degree Celsius
- Drive Type: Dual high-power H-bridge driver
- Module Size: 47 mm × 53mm
- Module Weight: About 29g

Pin Out



DRI0002 Pinout

Detailed Descriptions

Motor Terminal

The terminals are used to connected to the motors, which labeled "+" and "-" representing motor polarity.

LED

PWM: Power LED

Motor Status LED: Motors work normally, thus the IED will light up.

Power



VD: Power Supply 6.5V~12V;

VS: Motor Power Supply 4.8~46V;

GND: The common ground of Logic Power Supply and Motor Supply

Supply Switching Jumper



When jumper is shorted, logic power supply voltage is the same as the motor power supply. If motor power supply is less than 12V, you can set jumper shorted.

If motor power supply is more than 12V, dont't short jumper!

Motor Control Pins

E1,E2: Motor Enable Pin (PWM Control)

M1,M2: Motor Signal Pin. Eg: M1 = 0,the motor rotates in forward direction. M1 = 1,the motor rotates in back direction.


E	M	Run
LOW	LOW/HIGH	STOP
HIGH	HIGH	Back Direction
HIGH	LOW	Forward direction
PWM	LOW/HIGH	Speed

注: LOW = 0; HIGH = 1; PWM = 0~255

Tutorial

This tutorial shows you how to use I298N motor drive shield to drive two DC motors.

Connection Diagram



Sample Code

```
// # Editor
               : Lauren from DFRobot
 : 17.02.2012
 ^3// # Product name: L298N motor driver module DF-MD v1.3
  // # Product SKU : DRI0002
 o// # Version : 1.0
 7// # Description:
 ^{8}// # The sketch for using the motor driver L298N
  /// # Run with the PWM mode
<sup>11</sup>// # Connection:
12//#
           M1 pin -> Digital pin 4
13// #
              E1 pin -> Digital pin 5
14// #
              M2 pin -> Digital pin 7
15//#
             E2 pin -> Digital pin 6
16//#
              Motor Power Supply -> Centor blue screw connector(5.08mm 3p
^{17}connector)
18// #
              Motor A → Screw terminal close to E1 driver pin
19// #
              Motor B -> Screw terminal close to E2 driver pin
20//#
^{21}// # Note: You should connect the GND pin from the DF-MD v1.3 to your MCU
<sup>22</sup>controller. They should share the GND pins.
23// #
24
^{25}int E1 = 6;
^{26}int M1 = 7;
^{27}int E2 = 5;
^{28}int M2 = 4;
29
30void setup()
31{
32
      pinMode(M1, OUTPUT);
33
      pinMode(M2, OUTPUT);
34<sub>35</sub>
36void loop()
<sup>37</sup>{ 38
    int value;
39
    for(value = 0 ; value <= 255; value+=5)</pre>
```

PWM Principle

output_voltage = (on_time / off_time) * max_voltage

