

Load-Use Hazard Detection

- Check when using instruction is decoded in ID stage
- ALU operand register numbers in ID stage are given by
 - IF/ID.RegisterRs1, IF/ID.RegisterRs2
- Load-use hazard when
 - ID/EX.MemRead and
 - ((ID/EX.RegisterRd = IF/ID.RegisterRs1) or (ID/EX.RegisterRd = IF/ID.RegisterRs2))
- If detected, stall and insert bubble

26

How to Stall the Pipeline

- Force control values in ID/EX register to 0
 - EX, MEM and WB do **nop** (no-operation)
- Prevent update of PC and IF/ID register
 - Using instruction is decoded again
 - Following instruction is fetched again
 - 1-cycle stall allows MEM to read data for **1d**
 - Can subsequently forward to EX stage

27

Stalls and Performance


The BIG Picture

- Stalls reduce performance
 - But are required to get correct results
- Compiler can arrange code to avoid hazards and stalls
 - Requires knowledge of the pipeline structure

28

Branch Hazards

- If branch outcome determined in MEM




29

Control Hazards--How to handle?

- One software scheme: branch delay slot
 - Compiler inserts an instruction directly after a branch instruction that is independent of the branch inst.
 - No matter the branch is taken or not, that instruction should always be executed.
- One optimization
 - move branch addr calculation and condition test to ID stage
 - The lost 3 cycles is cut to 1.

30



31

Flushing instructions

- Move branch addr. calculation/condition testing to stage 2 (ID)
- Condition testing: use 32 XOR gates to compare bitwisely
 - delay: negligible
- IF.Flush==branch control line in single cycle datapath
- $F = \text{Zero} \bullet \text{IF.Flush}$ is used to control write of PC & IF.ID buffer
- If F=1, take branch by doing two operations
 - zero IF.ID buffer (flushing)
 - write PC with branch address
- If branch taken, lose one cycle
- CPI of beq

32

Reducing Branch Delay

- Example: branch taken

```
36: sub x10, x4, x8
40: beq x1, x3, 16 // PC-relative branch
               // to 40+16*2=72
44: and x12, x2, x5
48: orr x13, x2, x6
52: add x14, x4, x2
56: sub x15, x6, x7
      ...
72: ld x4, 50(x7)
```

33

