EXIT SWITCH PAUSE SWITCH WIRE CONTROL

Pause Wire always

heated

Long hold to exit program and turn off Pi

Running Wire controlled

by program