

Electrical Panel /

Short guide /

1 Safety first: de-energize before work.

- Check breakers/relays/terminals/wiring visually for heat, smell, discoloration.
- Verify tightening, labeling, and separation of PE/N.
- Diagnose by: power off -> measurement -> localization.

This PDF is a placeholder generated as plain text for the demo site.